


Major Compass - Spares Diagram

Cover & Lanyard - White 6903
- Black 6903-01




Cap - 2355



Compass screw - 6901



Binnacle Insert - 6948




Screw - 2351



Binnacle Assembly - White - 2660
- Black - 2660B

Quarter Hood & Light Block
Assembly
- White 6899
- Black 6909




Light Assembly 12v Clear - 6907
12v Red - 6907/01
6v Red - 6907/02
24v Red - 6907-03




Screw - 2615

Verge Ring - White 2297/A1
- Black 2297/A3




Dome - 2299

Screw - 0012



Container Assembly - White - 2664W
- Black - 2664




Ton Verge Gasket - 2300

Card - 2938


Pivot & Shadow pin assembly - 2683

Centre stem assembly - 2678




Gimbal screw - 2310

Lubber Line Carrier Assv - 2820



Basic Bowl Assembly -
White - Sail - 2801
Black - Sail - 2801B


Feed Screw Washer - 2324




Feed Screw - 3133




Diaphragm Gasket - 2624




Diaphragm - 6908



Diaphragm Mounting
Ring - 2619-AO



Screw - 0002



Fluid

Bayol-1 Litre
(2 Litres Required)

Magnet Set

7092

Radiant Compass – Spares Diagram



10BA X 3/32" Screw RD
HD – 0050 (2)



Prism Hood – 5723

Prism Bracket
Securing Screw
(6BA x 1/4" RD)

Basic Prism Bracket
Assembly – 5595



Prism - 5720


Complete Prism & Bracket Assembly - 2870



Verge Ring Securing
Screw (8) (6BA x 1/4" CSK HD) - 0005



Verge Ring – 5704



Verge Gasket - 5706


Verge Glass - 5705

Sight Wire Securing Screw (2)



Sight Wire

Pivot – 10000A-7



Card Assembly - 5667

'Brytlit' Capsule - 5761

'Brytlit' Capsule Holder Sec. Screw (10BA x 1/8" CSK HD)




Centre Stem Assembly - 5663

'Brytlit' Capsule Holder – 5739/01

Feed Screw - 3133




Feed Washer (Lead) - 2324



Bowl Assembly – 5581

Handle Securing Screw (qty. 3)
(No.2 x 3/8" RD HD Woodscrew) - 0068



Handle Assembly - 5698

Note Tablet - 5758

Fluid
Bayol – 1/2 Litre

Moore Compass – Spares Diagram

- Light Lead Assembly 12v (No Plug) – 2374-01
- 24v (No Plug) – 2374-02
- 12v (With Plug) – 2374-06
- 24v (With Plug) – 2374-07

Bearing Housing
Locking Handle –
2334

Bearing and Half Gimbal
Assembly – 3148

Shoulder Screw
Spacing Washer –
2346

Pillar
Bearing
Housing
Bracket –
2327

Corrector Magnet
Plate Assembly –
3147


Corrector Magnet Rack Securing
Screw (2BA x 1/4" RD HD)

Heeling Error Mag. Housing
Cap – 2355

Corrector Magnet
Screw (Plastic) – 2351

Bearing Housing Bracket Plate
– 2326

Compass Cover Assembly - 3154



Shadow Pin – 2339


Sight Assembly -
2376

4BA x 1/2"
Screw




Verge Ring - 2348

Shoulder Screw (7/16"
x 0BA) - 2345



Dome Assembly -
3153

Dome Gasket -
2344




Card & Float Assembly - 2371

Pivot –
10000A-7

Centre Stem Assembly - 4208

Lubber Line
Assembly –
3149

Lubber Line
Screw (8BA x 1/8"
CH HD) - 0018



Compass
Base
Assembly –
3189

Feed Washer - 2324

Feed Screw - 3133

Light Fitting Retaining
Plate – 2323/01

Diaphragm Cover – 2325/01

Light Fitting
Retaining Plate
Sec. Screw (4BA
x 1/8")

Diaphragm Cover Securing Screw
(4BA x 1/8")

Fluid

Bayol – 1 Litre

Magnet Set

7093

